

May 9, 1991

Group Chairman's Report of Investigation

Cockpit Voice Recorder

DCA-91-MA-022

ACCIDENT A.

Location: Colorado Springs Airport Colorado Springs, Colorado

March 3, 1991 Date:

1155 Eastern Standard Time (EST) Time:

Aircraft: United Airlines, Flight 585 Boeing 737-291, N999UA

GROUP B.

Chairman: Vincent M. Giuliana National Transportation Safety Board

Electronic Engineer

Eric A. Van Opstal Federal Aviation Administration (FAA) Member:

Aviation Safety Inspector

Leon E. Robert Member:

Boeing Commercial Airplanes

Senior Project Pilot

Mack R. Moore Member:

Air Line Pilots Association (ALPA)

William L. Rutherford Member:

United Airlines Standards Captain

SUMMARY C.

This transcript was derived from a Sundstrand Cockpit Voice Recorder (CVR) (model V557, S/N unknown) removed from